



NOTES:

1. ARBORIST REPORT RECOMMENDS REMOVAL AND REPLACEMENT OF NT1 AND NT2 DUE TO

POOR CONDITION, AND NT4 DUE TO ITS UNSUITALBE LOCATION FOR LONG TERM RETENTION
2. SMALL TREE = UNDER 8.0 m (25') HT; LARGE TREE = UP TO 15.0 m (50') HT













DOWNLIGHTING CHARACTER IMAGES





TRELLIS CHARACTER IMAGE AND DETAIL










ROOFTOP TREES IN PLANTERS



RECTANGULAR PLANTERS

