

EXTERIOR CHANGES

Location	Previous	Proposed
Building A north elevation level 1.	Wider shopfront windows.	Storefront windows to be narrowed to match existing heritage brick condition. The condition was concealed behind the 1970s aluminium shopfronts and recently uncovered during construction. Change approved through Heritage Alteration Permit.
Building A south elevation level 1.	6' wide curtain wall.	Curtain wall changed to double doors to allow for greater occupant load in restaurant. Egress doors need to be 1/3 of the maximum diagonal dimension of the suite away from each other.