Perriwinkle

**Evergreen Clematis** 

Boston Ivy

NOTES:

Vinca minor

Clematis armandii

Parthenossissus Tricus. Veitchii

Plant material, installation and maintenance to conform to BCSLA/ BCLNA standard (current edition).

All growing medium to comply to BCLSA/ BCLNA standard designation "1P - Level-1 Well Groomed Areas".


Underground irrigation system to be installed. Irrigation materials and installation to conform, as a minimum, to BCSLA/ BCLNA Standard (current edition) and IIABC Standards. All irrigation piping under hardsurfaces to be sleeved.


Fencing to be built as shown on plan; portions of fencing along sideyards to be built with trellis top where shown.

All existing trees located on plan are approximate. Size and dripline of trees are not shown, and should be verified by a surveyor and /or arbourist where necessary. General contractor and Landscape contractor are to make themselves familiar with The Project Arborist's Tree Management Plan (TMP) and Tree Protection Plan (TPP). Arbourist to install tree protection fencing for boulevard tree where necessary.

#2 Pot / Staked

#2 Pot / Staked





NORTH PARK ST

NORTH PARK ST

SKL.01
10.SEPTEMBER.2021
1:100
LATEST REVISION: 15.SEPTEMBER.2021

1048 NORTH PARK ST LANDSCAPE LAYOUT



River stone and planting highlight area

Unit pavers walkway for pathway

to bicycle parking area

River stone and planting highlight area

Proposed planting area before municipal sidewalk

Bicycle parking area #1

Bicycle parking area #2

MULTI-RESIDENTIAL DEVELOPMENT :: 1048 NORTH PARK STREET :: SKL.01 :: landscape layout